



P/N: 60-13-2M06-018 (REV. A)

Description: SMA Right Angle Male Solder for RG402/.141 Cable




STEP 1

- a. Slide the Heatshrink Sleeve onto the cable (option).
- b. Strip the cable according to the dimensions as below.




STEP 2

- a. Slide the cable into the Main Body.
- b. Solder the cable's inner conductor.
- c. Solder the cable's outer conductor onto the Main Body.



STEP 3

- a. Screw the Back Nut onto the Main Body.
- b. Slide the Heatshrink Sleeve over the Main Body and heatshrink it in place (option).



Note: Dimensions in millimeters (mm).